

## **Landlord Gas Safety Record**

Cert. No. 60653

**North Somerset Gas Services Ltd** 

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / I	Job Address						Customer / Landiord									
Engineer	Engineer Martin Williams			Name	Name Mr M Owen											
Company	North Somerset Gas Services Ltd			Address	5					Company	Mcgowan Investments					
Address	11		Trendlewood Park Bristol					Address	Catherine House							
	Embercourt Drive								Harborough Road							
	Backwell								Northants							
	Bristol			Post Code						Totaland						
Post Code BS48 3HU			Tel. No						Post Code	NN6 9BX						
Tel No. 07944975650										Tel. No						
Gas Safe Reg 191360																
ID Card No.	4461190															
ib cara ivo.	4401190															
Appliance D	etails				Inspe	ction Details	5									
Location	Appliance Type	Make	Mode	el Flue	ype Landlord's	Appliance Inspected	oted Operating Pressure (mbar)	Heat Input (kW/h)	High Combustion Reading	ion Low Combustion Reading		Ventilation Provision	Visual condition of flue and	Flue Performance	Appliance Serviced	Appliance safe to use
					Арриансе		(IIIbai)		Ratio CO	CO2 Ratio CO CO:	correct operation	satisfactory	termination satisfactory	test	Serviced	to use
1 Clastons	Deller	V = 111 = == k	F 4 1	Dur. 20	. V	V	22	21.22	ppm			V		D	NI-	V
1 Cloakroo	om Boiler	Vaillant	Ecotec I	Pro 28 R	Yes	Yes	22	21.23	0.0004 44	9.1 0.0001 5 8.3	Yes	Yes	Yes	Pass	No	Yes
2 3																
4																
5																
6 Lebels and Warrier Nation Land																
Defects / Ide			Labels and Warning Notice Issued				CO Alarm(s) Smoke Alarm(s)									
1								NA		CO Ala (a) Eta	L	V	Caralia	\\/-\	1	NA
3										CO Alarm(s) fit	tea	Yes	Smoke A	Alarm(s) fitt	ea	NA
	4									CO Alarm(s) te	ested _		Smoke A	Smoke Alarm(s) tested		
5									and Satisfactory Pass				and Satisfactory			
6																
Emergency Co	ntrol Accessible Yes G	as Tightness Satisfactory Ye	ac	Commen	ts					'						
			.5		_											
Gas installation	n Pipework Visual Inspect	on Satisfactory Yes														
Equipotent	ial Bonding Yes															
NEYT INCDECT	ON DUE ON OR BEFORE	12-Aug-2021														
NEXT INSPECT	ON DUE ON OR BEFORE	12 / lug 2021														
Signatures																
Issued by:	Signed	1	ı	Received Signe	d					Date	06-Ju	l-2020				
	MH			oy:												
Print Name	Martin Willia	ms	ı	Print Name	M Wi	liams										