

Landlord Gas Safety Record

Cert. No. 60740

North Somerset Gas Services Ltd

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer					Job Address							Customer / Landiord						
Engineer	Engineer Martin Williams			Name							Name	Mr M Owen						
Company	Company North Somerset Gas Services Ltd			Address	44				Company	Mcgowan Investments								
Address	11 Embercourt Drive				Tre	Trendlewood Park					Address	Catherine House						
					Bri	Bristol						Harborough Road						
	Backwell											Northants						
	Bristol			Post Code														
Post Code BS48 3HU			Tel. No							Post Code	NN6 9BX							
Tel No. 07944975650										Tel. No								
Gas Safe Reg 191360																		
ID Card No. 5028837																		
Appliance D	etails					Inspec	tion Details											
Location	Appliance Type	Make	Mode	el	Flue Type	Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combustion	n Low Combustion Reading	Safety device(s) correct	Ventilation Provision	Visual condition of flue and	Flue Performance	Appliance Serviced	Appliance safe to use	
						Арриансс		(mbar)		Ratio CO	CO2 Ratio CO CO2	operation	satisfactory	termination satisfactory	test	Scrviccu	to use	
1	nest Delles	Maillant.	F	C10/2F	D.C.	V	Marral	21	11	ppm			V		D	NI-	V	
1 Compartn	nent Boiler	Vaillant	Ecomax	618/2E	RS	Yes	Visual	21	11	0.0006 56	9.7 0.0006 54 9.7	Yes	Yes	Yes	Pass	No	Yes	
3																		
4																		
5																		
6																		
	.16. 1							Labole a	nd Marning No	atica Iccuad				C I	AL /	1		
Defects / Ide	entified					Labels and Warning Notice Issued			CO Alarm(s)	Smoke	Smoke Alarm(s)							
1									NA									
2											CO Alarm(s) fit	ted	Yes	Smoke	Alarm(s) fitt	ed	NA	
3																		
4										CO Alarm(s) tested and Satisfactory			Smoke Alarm(s) tested and Satisfactory			NA		
5											and Salisiación	У		and Sat	isiactory			
Ü																		
Emergency Co	ntrol Accessible Yes (Gas Tightness Satisfactory Ye	es	Comm	nents													
Gas Installation	n Pipework Visual Inspect	ion Satisfactory Yes																
		ion dutionactory 100																
Equipotent	ial Bonding Yes																	
NEXT INSPEC	TION DUE ON OR	15-Aug-2022																
BEFORE																		
Signatures																		
Issued by:	Signed	٨.	F	Received Si	gned						Date	05-A	ug-2021					
	Marko		k	oy:														
Print Name	Martin Willia	ams	F	Print Name		M Will	ams											